



MAIN HARNESS WIRING 2010 Zero DS

- NOTES
1. Symbols are just representative, not following any standard
 2. Connector pinouts are relative; use wire colors to identify pin 1
 3. Diagram has been double-checked, but might contain errors
 4. I am not responsible for any damage that may occur from the use of this diagram

Color codes

- B - Black
- Br - Brown
- G - Green
- L - Blue
- O - Orange
- R - Red
- W - White
- Y - Yellow

